

EXIT DEVICE INSTALLATION INSTRUCTIONS

K-111 SWITCH KIT

DOR-O-MATIC SERIES 990 AND 1090 EXIT DEVICES
SWITCH MONITORS EGRESS BY PUSHBAR ACTIVATION
OF EXIT DEVICE

ELECTRICAL SPECIFICATIONS

- SPDT MONITOR SWITCH
- CONTACT RATING: 4 AMP @ 250VAC

COLOR CODE FOR WIRES

- YELLOW WIRE: COMMON
- RED WIRE: NORMALLY OPEN
- GRAY WIRE: NORMALLY CLOSED

INSTALLATION INSTRUCTIONS

- STEP 1: REMOVE HINGE STYLE CASE.
- STEP 2: PLACE SWITCH ASSEMBLY INTO DEVICE AS SHOWN. ASSEMBLY FITS OVER TOP OF EXISTING HOLE.
SET SCREW OF SWITCH KIT BRACKET FITS INSIDE HOLE.
- STEP 3: MAKE SURE SWITCH ARM IS PLACED ON CORRECT SIDE OF ACTIVE MECHANISM AS SHOWN.
- STEP 4: SWITCH KIT IS CAPTURED BETWEEN DOOR SURFACE AND HINGE STYLE MAKE SURE BRACKET IS FLUSH WITH MOUNTING SURFACE.
- STEP 5: CHECK FOR PROPER SWITCH ACTIVATION WHEN PUSHBAR IS FULLY DEPRESSED, REFER TO COLOR CODE CHART FOR PROPER WIRING FOR APPLICATION.
- STEP 6: MAKE SURE COLOR CODE FOR WIRES CHART IS USED FOR PROPER HOOK-UP OF SWITCH CONTACTS.

