


1103-04 HINGE TEMPLATE

MODEL 1114, 1116, 1118 & 1120 CONCEALED ELECTRIC THROUGH WIRE & MONITOR & CONCEALED AIR TRANSFER



FOR USE WITH ALL MANUFACTURERS

5.0" FULL MORTISE 3 KNUCKLE BALL BEARING

HINGES STANDARD AND HEAVY WEIGHT



HINGES ARE SHOWN FROM THE FRONT SIDE. HAND HINGE AS SHOWN.



HINGES ARE NON-LOAD BEARING AND MUST BE MOUNTED IN THE CENTER POSITION ONLY.